Inspection Report

By Sri.K. Manjunath
Retd. Executive Engineer

Name of Work: Filling Pot holes in main and cross roads of Bagalugunte in Ward No.14

B.R.No: 240/15-16

Estimate Cost: 13.00 Lakhs

Bill Amount: 11,59,879.00

Date of Inspection 12-12-2017

Observation and Conclusion:

The above said work "Filling potholes in main and cross roads of Bagalagunte ward no 14" was shown to me by the Concerned ward Engineer

The above said work is inspected by me along with the Concerned ward Engineer

The quality of the work done is Satisfactory

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of Work: Filling Pot holes in main and cross roads of Bagalugunte in Ward No.14

BR No. 240, Date.08.07.2016

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರ
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ ಪಬ್ಲಿಕ್ ಹೆಲ್ತ್ ಬೆಂಗಳೂರು

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD
PUBLIC WORKS DEPARTMEN

Name of Work: Filling Pot holes in main and cross roads of Bagalugunte in Ward No.14

BR No. 240, Date.08.07.2016

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT